


GS913

Резьбовые штифты

Материал: DIN 913-45H



Номер d x L	L	d	t	S
GS913 3-4	4	M3	2,5	1,5
GS913 3-5	5	M3	2,5	1,5
GS913 3-6	6	M3	2,5	1,5
GS913 3-8	8	M3	2,5	1,5
GS913 3-10	10	M3	2,5	1,5
GS913 3-16	16	M3	2,5	1,5
GS913 4-4	4	M4	2,5	2,0
GS913 4-5	5	M4	2,5	2,0
GS913 4-6	6	M4	2,5	2,0
GS913 4-8	8	M4	2,5	2,0
GS913 4-10	10	M4	2,5	2,0
GS913 4-12	12	M4	2,5	2,0
GS913 4-16	16	M4	2,5	2,0
GS913 4-20	20	M4	2,5	2,0
GS913 5-5	5	M5	3,0	2,5
GS913 5-6	6	M5	3,0	2,5
GS913 5-8	8	M5	3,0	2,5
GS913 5-10	10	M5	3,0	2,5
GS913 5-12	12	M5	3,0	2,5
GS913 5-16	16	M5	3,0	2,5
GS913 5-20	20	M5	3,0	2,5
GS913 5-25	25	M5	3,0	2,5
GS913 6-6	6	M6	3,5	3,0
GS913 6-8	8	M6	3,5	3,0
GS913 6-10	10	M6	3,5	3,0
GS913 6-12	12	M6	3,5	3,0
GS913 6-16	16	M6	3,5	3,0
GS913 6-20	20	M6	3,5	3,0
GS913 6-25	25	M6	3,5	3,0
GS913 6-30	30	M6	3,5	3,0
GS913 6-40	40	M6	3,5	3,0
GS913 8-8	8	M8	5,0	4,0

Номер d x L	L	d	t	S
GS913 8-10	10	M8	5,0	4,0
GS913 8-12	12	M8	5,0	4,0
GS913 8-16	16	M8	5,0	4,0
GS913 8-20	20	M8	5,0	4,0
GS913 8-25	25	M8	5,0	4,0
GS913 8-30	30	M8	5,0	4,0
GS913 8-35	35	M8	5,0	4,0
GS913 10-10	10	M10	6,0	5,0
GS913 10-12	12	M10	6,0	5,0
GS913 10-16	16	M10	6,0	5,0
GS913 10-20	20	M10	6,0	5,0
GS913 10-25	25	M10	6,0	5,0
GS913 10-30	30	M10	6,0	5,0
GS913 10-35	35	M10	6,0	5,0
GS913 10-40	40	M10	6,0	5,0
GS913 10-50	50	M10	6,0	5,0
GS913 12-12	12	M12	8,0	6,0
GS913 12-16	16	M12	8,0	6,0
GS913 12-20	20	M12	8,0	6,0
GS913 12-25	25	M12	8,0	6,0
GS913 12-30	30	M12	8,0	6,0
GS913 12-35	35	M12	8,0	6,0
GS913 12-40	40	M12	8,0	6,0
GS913 12-50	50	M12	8,0	6,0
GS913 16-16	16	M16	10,0	8,0
GS913 16-20	20	M16	10,0	8,0
GS913 16-25	25	M16	10,0	8,0
GS913 16-30	30	M16	10,0	8,0
GS913 16-35	35	M16	10,0	8,0
GS913 16-40	40	M16	10,0	8,0
GS913 16-50	50	M16	10,0	8,0

www.system.com.ru